BRONZE METAL POWDER



FP-BRZ



Product Description

Highly pure, very fine 200 mesh irregular bronze metal powder suitable for a range of applications including resin-casting (cold casting), decorative coatings and powder metallurgy.

How to use

Use In Cold-Casting / Resin Casting

Add bronze powder to castings resins such as polyurethane Fast-Cast resins, polyesters or epoxies for an authentic metallic bronze appearance and feel.

Added to the whole of the resin mix, bronze powder will increase the density of a casting (making it feel heavier) as well as its thermal conductivity (making it feel colder). Alternatively, it can be added in higher ratios to only a thin surface layer by slush-casting or rotationalmoulding, giving a very metallic surface to a casting that can then be back-filled with unfilled resin.

Mix Ratios

A ratio of at least 50% bronze powder (by weight) would be required to result in a significantly metallic appearance. Higher ratios, up to the limit of pourability, will yield a more impressive metallic appearance and feel.

When adding metallic powders to polyester or vinylester resin systems it is important to catalyse the resin prior to adding the metal powder so as to avoid any adverse reaction (rapid oxidisation) of the metal powder by the catalyst.

Such oxidisation or other adverse reactions are unlikely to occur with polyurethane or epoxy resins but it may still be a good idea to mix the resin and hardeners together before adding the metal powder.

Revealing the Appearance

After casting, the metallic appearance will not be clear or vivid because the metal particles will be obscured behind a thin layer of resin.

Easy Composites Ltd

Jnit 39, Park Hall Business Village, Stoke on Trent, Staffordshire, ST3 5XA Jnited Kingdom. Neb www.easycomposites.co.uk Easy Composites EU B.V. (EU Customers) Beneluxbaan 16, Rijen, 5121 DC Netherlands Web www.easycomposites.eu

Bronze Metal Powder - Technical Datasheet - 16/05/2024

To reveal the metallic appearance, the casting can be rubbed with an abrasive pad or wire-wool.

Patinating (Rusting)

After exposing bronze particles on the surface of a casting, the bronze on the surface will patina (rust) in the same way that a conventional bronze product would which means that it will quickly take on the distinctive dull turquoise colour of patinated bronze.

Specification

Particle Size Distribution - Sieve

Mesh	Size (µm)	Min - Max
+100	+150	Trace
+200	+75	0.0 - 4.0%
-200	-75	Balance

Chemical Analysis

Element	Result (%)
Tin	10.0 - 12.0
Copper	Balance

Physical Properties

Property	Unit	Result
Colour	-	Metallic Brown
Format	-	Powder
Particle Size	Mesh	200

Disclaimer

This data is not to be used for specifications. Values listed are for typical properties and should not be considered minimum or maximum.

Our technical advice, whether verbal or in writing, is given in good faith but Easy Composites Ltd gives no warranty; express or implied, and all products are sold upon condition that purchasers will make their own tests to determine the quality and suitability of the product for their particular application and circumstances.

Easy Composites Ltd shall be in no way responsible for the proper use and service of the product, nor for the safeguarding of personnel or property, all of which is the duty of the user. Any information or suggestions are without warranty of any kind and purchasers are solely responsible for any loss arising from the use of such information or suggestions. No information or suggestions given by us shall be deemed to be a recommendation to use any product in conflict with any existing patent rights. Before using any of our products, users should familiarise themselves with the relevant technical and safety datasheets provided by Easy Composites Ltd.